

lot 5
Recommendations that would protect the salmon.



- Lot 5:
- ① Salmon have spawned in Stream E2 (point marked *) but are blocked from going further North by a gravel plug. This spawning channel could and should be restored.
 - ② Glacial pond E8 is full year round and was cut off from E3 by the building on the corner. This cut-off causes flooding issues which could be resolved by reconnecting Pond E8 to E3.
 - ③ We respectfully ask that Lot 5 NOT be industrialized and that the streams be restored for spawning salmon!

161844 CANADA INC.
Dunsmuir DR

envirowest